Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE2203/1
Work Order Type: Weatherization
Audit Name: Audit (20)

CLIENT INFORMATION

Client Name: Watkins, Clinton Address:
Client ID: 50005DE2203

Alt. Client ID:

CLIENT CONTACT INFORMATION

Watkins, Clinton (901) 466-7994 Applicant/Person of Record

<u>AGENCY INFORMATION</u>

Agency: Delta Human Resource Agency

Agency Phone: (901) 476-5226

Address: P. O. Box 634 **Fax:** (901) 476-5258

Agency Contact: Martin, Darrell L. Work Phone:

Cell Phone: (901) 262-8090

Email Address: DarrelllMartin@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Page 1 of 5

	olace (2) 29" x 28" Broke 0 #2	en Panes i	in	Componen	ts		ı	nspected
Comment Replac	e (2) 29" x 28" Broken pa	nes in bott	tom sa	sh				
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Material	Each	1					
2 Labor	Labor		1					
Other Detail								
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								
12	place 29" x 28" Broken F 29" x 28" broken pane in		D#	Componen				nspected
Comment Replace	29" x 28" broken pane in	top sash		Estimated	,	Qty	Actual	
12			Qty	•		Qty		Inspected
12 Comment Replace # Material / Labor	29" x 28" broken pane in Description / Comment	top sash <i>Units</i>	Qty	Estimated	,	Qty	Actual	
12 Comment Replace # Material / Labor 1 Windows 2 Labor	29" x 28" broken pane in Description / Comment Material	top sash <i>Units</i>	Qty 1	Estimated	,	Qty	Actual	
12 Comment Replace # Material/Labor 1 Windows	29" x 28" broken pane in Description / Comment Material	top sash <i>Units</i>	Qty 1	Estimated	,	Qty	Actual	
12 Comment Replace # Material / Labor 1 Windows 2 Labor	29" x 28" broken pane in Description / Comment Material	top sash <i>Units</i>	Qty 1	Estimated	,	Qty	Actual	
12 Comment Replace # Material / Labor 1 Windows 2 Labor	29" x 28" broken pane in Description / Comment Material	top sash Units Each	Qty 1 1	Estimated	,		Actual	

Measure 3 Rep	olace 29" x 28" Broken F	Pane in W	D #3	Componen	ts		ı	Inspected
Comment Replace	e 29" x 28" Broken pane i	in bottom	sash					
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Material	Each	1					
2 Labor	Labor		1					
Other Detail						1		
			Measur	e Sub Total:		,	Sub Total:	
Block & Seal ar Caulk \	& Seal Air Conditioner in V & Seal Air Conditioner in V round all plumbing pipes u Windows # 1 thru # 12 round all plumbing pipes u	VD # 7 Inder kitch						
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	Measure 5 DW omment	/H Tank Insulation			Componen	ts		1	Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 6 DW omment	/H Pipe Insulation			Componen				Inspected
C	omment	·	Unito	O4v	Estimated	1	044	Actual	
<i>C</i> :		/H Pipe Insulation Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	-		Qty		Inspected
C (omment Material / Labor	Description / Comment			Estimated	1	Qty	Actual	
C # 1 2	omment Material / Labor Insulation	Description / Comment DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
C # 1 2	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
C # 1 2	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
# 1 2	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each Each	1 1	Estimated	1		Actual	

Report Run On: 5/23/2010

Measure 7 Stor	m Windows		Components WD05,WD06,WD07, Insp WD10,WD01,WD02, WD03,WD11,WD12, WD08,WD09					
Comment				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	SqFt	146.7					
2 Labor	Storm Window	SqFt	146.7					
3 Other	Storm Window	Each Window	11					
Other Detail						¬		
			Moosur	e Sub Total:]	Sub Total:	
Field Notes:								
Measure 8 CO Comment	Monitor is Needed			Compone	nts			Inspected
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								

Client Name: Watkins, Clinton Client ID: 50005DE2203 Alt. Client ID:

Report Run On: 5/23/2010